Photo Sensor

# **PS/PW** series

#### **INSTRUCTION MANUAL**

We appreciate you for purchasing HanYoung NUX Co.,Ltd product. Before using the product you have purchased, check to make sure that it is exactly what you ordered. Then, please use it following the instructions below.

#### MAIN PRODUCTS

- DIGITAL : Temperature Controller, Counter, Timer, Speedmeter,

Tachometer, Panel Meter, Recorder

- SENSOR : Proximity Switch/Photo Electric Sensor, Rotary Encoder, Optical Fiber Sensor,

Pressure Sensor - ANALOG : Timer, Temperature Controller

#### **HEAD OFFICE**

1381-3, Juan-Dong, Nam-Gu Incheon, Korea TEL: (82-32)876-4697 FAX: (82-32)876-4696



# ■ Safety information

Before you use, read safety precautions carefully, and use this product properly. The precautions described in this manual contains important contents related with safety; therefore, please follow the instructions accordingly. The precautions are composed of DANGER, WARNING and CAUTION.

# **A** DANGER

Do not touch or contact the input/output terminals because they may cause electric shock.

## **M** WARNING

- To prevent defection or malfunction of this product, supply proper power voltage in accordance with the rating.
- Since this product is not designed with explosion-protective structure, do not use it at any place with flammable or explosive gas.
- Remove this product while the power is off. Otherwise, it may cause malfunction or electric shock.
- Due to the danger of electric shock, use this product installed onto a panel while an electric current is applied.

# **A** CAUTION

- Earth the Frame Ground(FG.) in case of using the switching regulator.
   Otherwise, they may cause wrong operating.
- When using the sensor under the light such as fluorescent lighting or mercury lamp with high frequency, block it with a light trap and avoid the lens from facing the light directly.
- 3. Do not use an auto tranformer. Use an insulating transformer.
- 4. If the cable needs to be extended, use over 0.3  $_{\mbox{\scriptsize mri}}$  and be cautious of a possible sudden drop in voltage.
- Separate high voltage cable and power line from sensor wire. Be cautious since using a same pipe arrangement for the wire could cause malfunction.
- 6. Avoid continuously switching the power source On and Off.
- This product is equipped with a structure (IP67), which allows partial waterproof but do not use this product under water at all times.
- 8. When the lens of the photo sensor is contaminated by foreign substance, use a dry cloth to wipe off the substance. Never use thinner or organic solvents.


# **■** Ordering Information

MODEL	Suffix Code				Description					
P					PS : Photo Sensor Small size PW : Photo Sensor Small Wice Type					
	T		-		Through Beam Type					
	М	M			Retro reflection Type					
Detection	R	2			Diffuse reflectio	<u> </u>				
Dottootion	Z				Convergent Bea	• •				
	D	D ! !				ergent Beam Type				
		1				1 m				
		7	<del>.</del>		Through Beam	7 m				
		10			J	10 m				
		2			Retro reflection	2 m				
	7	i			70 mm					
		30			Diffuse	300 mm				
		40			reflection	400 mm				
Sensing		4	i I		Convergent	1 ~ 40 mm				
distance		3	i I		Beam	3 ~ 30 mm				
		3				10 ~ 30 mm				
		4				10 ~ 40 mm				
		5	i i		Distance	10 ~ 50 mm				
		10 ¦			Convergent	10 ~ 100 mm (Only for PW series)				
		15			Beam	10 ~ 150 mm (Only for PW series)				
		20	i I			10 ~ 200 mm (Only for PW series)				
LED indic	LED indicator R				Infrared LED					
LLD IIIdio					Red LED					
Outr	Output			N	NPN output					
Julip				Р	PNP output					


# ■ Specification

Туре		Through beam			Retro reflection Diffuse reflection			Convergent beam		Distance convergent beam							
Model	NPN type	_	PS-T7N	PS-T10RN	PS-M2RN	PS-R7N	PS-R30N	PS-R40RN	PS-Z4N	PS-Z3RN	PS-D3RN	PS-D4RN	PS-D5RN	PW-D10RN	PW-D10N	PW-D15N	PW-D20N
iviodei	PNP type	PS-T1P	PS-T7P	PS-T10RP	PS-M2RP	PS-R7P	PS-R30P	PS-R40RP	PS-Z4P	PS-Z3RP	PS-D3RP	PS-D4RP	PS-D5RP	PW-D10RP	PW-D10P	PW-D15P	PW-D20P
Range		1 m	7 m	10 m	0.1~2 m	70 mm	300 mm	400 mm	1~40 mm	3~30 mm	10~30mm	10~40mm	10~50mm	10~10	0 mm	10~150 mm	10~200 mm
Detect	table object		Ø6 mm	•	Ø20 mm	* White paper 100 ×100 mm	*White pape	r 200 × 200 mm	*White paper	100 ×100 mm	* White p	paper 50 ×	50 mm	*Wh	ite paper 1	00×100 m	ım
Pow	er supply					+12 ~ +24 V DC $\pm$ 10 % (Ripple $\pm$ 10 % (Max.))							•				
Curre Consu		Max.23mA	Max.20 mA	Max.23 mA	Max.	Max.	Max.	May 2	Max. 25 mA 23 mA		Max. 30 mA		Max. 30 mA				
-tior	ı ˈ   Rcvr	Max.20mA	Max.20 mA	Max.20 mA	23 mA	28 mA	23 mA	IVIAX. Z									
Outp	Uutput		NPN Open collector / PNP Open collector output, Sink current 100 mA, 30 V DC Max. , Short protection circuit														
mod	e Stability output	NPN Open collector output, Sink current 50 mA, 30 V DC Max. (except for PNP type)															
Outp	out mode	Light ON or Dark ON selectable by convert switch															
Resp	onse time	Max. 0.7 ms															
Hys	steresis	is				Max. 20 % of operating distance							Max. 10 % of operating distance				
Ligh	ht source Infrared LED Red		Red I	LED	Infrared LED Red LED			Infrared LED		Red LED			Infrared LED				
LED	indicator		Control output indicator : Red LED, Stability output : Green LED (Power : Red LED in Through beam type) (except PW series)														
Amb	ient light	Sun lights : Max. 5000 lux															
Ambien	t temperature	e -25 ~ +55 ℃															
Ambie	nt humidity	35 ~ 85 % RH															
Case	protection								IP	67							
Vil	bration					10 ~	55 Hz, Do	uble amplitu	ide : 1.5 m	nm, X · Y · Z	Zeach dire	ctions for 2	hours				
Ir	mpact						50	0 m/s² (50 G)	X · Y · Ze	ach directi	ons for 3 ti	mes					
		Trns:	⊘3/2C(ler	ngth : 2 m)		NPN type: Ø3/4C (length: 2 m)					)) NP			NPN tv	PN type: Ø4/4C (length: 2 m)		
(	Cable		Rcvr: Ø3/4C(length: 2 m)			PNP type: Ø3/3C (length: 2 m)							PNP type: Ø4/3C (length: 2 m)				
		(PNP	type Rcv	r Ø3/3C)	1 W. type . Mo/30 (length . 2 m)							1 141 type : Ø=/30 (length : 2 m)					
М	aterial	CASE : PC, Lens Cover : PC															
V	Veight	Trns. & Rcvr. : 50 g each Approx. 50 g Approx. 80 g															
* nor	n-glossy an	d white n	aner	·						-				·	-	-	

■ Dimension Unit: mm




# **■** Control Output



In the transmitter of Through-Beam, only power input is available. (For, PW series, only distance convergent Beam is available)


# ■ About the stability output

It can be used as check the initial movement, check environmental changes after set up or level dropping during use. When it does not reach 120 % (stable light penetration area) after passing the operating level, the control output will see it as OFF and generate power. (However, there is no stability output of power for the PNP output type.)




#### Indicators

- The output indication light (red LED) and the stability indication light (green LED) are indicate the level of the picture.
- Detect object must be in the stable light penetration and shield.
   It can be check by repeating the light penetration and shied after adjusting the optical axis or sensortivity.
- When setting up in the stable area, high reliability can be obtained in regards



to changes such as environmental changes after the set up. When using SELECT S/W as L.ON, red LED will go on for light penetration. When using it as D.ON, the red LED will go off for light shielding.



# ■ How to adjust the sensitivity

(During the light penetration operating - adjustment for reflective object in background)


- First, place the object at the designated location and set the location of the operating indication light to point 

   while gradually increasing the volume for the sensitivity adjustment.
- 2. In the absence of an object, gradually lower the volume of sensitivity adjustment from the maximum and set point (b) at the point which is light off. (When the movement indication light does not light on even at the maximum sensitivity level, point (b) will be the maximum point.)



# ■ About the detecting direction (Distance Convergent Beam type)

There is directional in the divided photo diode. So, be cautious of not available Left & Right detecting direction.



Impossible directions for use: The product can be used for the up and down directions of the surface within the distance set up by the volume for detecting distance adjustment.

# ■ About the background object (Distance Convergent Beam type)

- In case of malfunction can be occurred due to the angle of the background object, establish aslant the sensor for the object with gloss or frontal form.
- 2. When detecting a glossy object (surface with shine), slant the sensor about 5 ~ 10° in the set up. (Picture 1)
- 3. If there is a frontal form on the bottom of the sensor, movements might be unstable. Therefore either slant the sensor or maintain a certain distance within the set up to avoid being affected by the bottom side. (Picture 2)
- 4. In case of the color or quality of sensor changing extremely, the detecting side and the surface of the object must be set parallel to one another for use. (Picture 3)









# ■ Sensing Distance (Diffuse reflection type)

■ Red LED type (R40RN)



#### ■ Infrared LED type (R30N)



광전자 센서 -

# PS / PW series

(주)한영넉스의 제품을 구입하여 주셔서 대단히 감사합니다. 제품이 맞는지 확인하시고 아래의 항목에 따라 사용하십시오.

(주)한영넉스 인증현황





#### • 본사/공장

인천광역시 남구 주안동 1381-3 TEL. 032)867-0941 FAX. 032)868-5899 ☎ 크로바써비스 080-979-1010 http://www.hynux.com



#### 인전상 주의사항

사용전에 안전상의 주의를 잘 읽어 주시고 올바르게 사용하여 주십시오 여기에 표시된 주의사항은 안전에 관한 중요한 내용을 기재하고 있으므로 필히 지켜주 십시오. 안전주의사항은 위험, 경고, 주의로 구분하고 있습니다.

#### ◢ 위 험

입력 단지는 감전의 위험이 있으니 신체 및 통전물이 절대로 접촉되지 않도록 하십시오.

# ▲ 경 고

- •본기기의 피손방지 및 고장방지를 위하여 정격에 맞는 전원전압을 공급하여 주십시오.
- 방폭구조가 아니므로 가연성,폭발성 가스가 있는 장소에서는 사용하지 마십시오.
- •본기기의 탈착은 전원을 OFF한 후 조치하여 주십시오. 감전, 오동작, 고장의 원인이
- 감전될 위험이 있으므로 통전 중 본기기를 판넬에 설치된 상태로 사용하여 주십시오

# 🚹 주 의

- Switching Regulator를 사용하는 경우에는 반드시, 프레임 그라운드 (F.G)단지를 접 지하여 주시고, 접지하지 않으면 전원의 스위칭 노이즈로 인한 오동작이 발생할수 있 으므로 주의하여 주십시오.
- 형광등이나 인버터등의 주변에는 설치를 삼가하여 주시고, 고주파 점등형의 기기는 광전자 센서의 변조 주파수에 가까운 광이나 노이즈를 발생시켜 제품의 오동작을 하 게하는 원인이 되오니 주의하십시오
- •제품의 인가전원의 안정성을 유지하기 위해서는 오토트랜스를 사용하지 마시고, 반 드시 절연트랜스를 사용하여 주십시오.
- Cable을 연장시킬때에는 가능한 굵은 선 (0.3㎡ 이상)을 사용하여 주시고, 이때 전압 강하에 주의하여 주십시오.
- 고압선 및 동력선과 센서의 배선은 반드시 분리해서 따로 배선하여 주십시오.
- 제품의 전원을 연속적으로 ON/OFF하면 제품의 수명이 단축되거나 오동작의 원인이 되오니 주의하십시오.
- •본제품은 IP67의 방수구조이나 항상 물이 있는 장소나 수중에서는 사용할수 없습니다.
- •제품의 렌즈나 CASE의 청소는 마른 천등을 사용하여 가볍게 닦아주시고, 신나나 알 콜 등의 유기용제는 사용하지 마십시오.

트기형 미리바시형

#### 형명구성

형 명	형 번				내 용					
P□				П	PS: Photo Sensor Small Type					
					PW:Photo Sensor Small Wide Type					
	Ti i			Through Beam (특	투과형)					
	М				Retro reflection (1	Mirror반사형)				
검출방식	R				Diffusereflection	(확산반사형)				
	Z				Convergent Beam	(한정반사형)				
	D				Distance Converg	ent Beam [측거형(거리조정반사형)]				
		1				1 m				
		7			투과형	7 m				
		10				10 m				
		2			미러반사형	2 m				
	7					70 mm				
		30			확산반사형	300 mm				
		40				400 mm				
검출거리		4			കിചിവി വികി	1 ~ 40 mm				
пен		3			한정반사형	3 ~ 30 mm				
		3				10~30 mm				
		4				10~40 mm				
		5			측거형	10~50 mm				
		10			(거리조정반사형)	10~100 mm (PW series에 한함)				
		15				10~150 mm (PW series에 한함)				
		20				10~200 mm (PW series에 한함)				
			無		Infrared LED (적	외선)				
발광소지	ł	R			Red LED(적색)					
출 력			N	NPN output type						
			Р	PNP output type						


추거시(거리조저바시형)


# 정 격

AI.

PNP vpe   PS-T1N   PS-T10RN   PS-M2RN   PS-R30N   PS-R40RN   PS-R40RN   PS-Z4N   PS-Z3RN   PS-D3RN   PS-D4RN   PS-D5RN   PW-D10RN   PW-D10N   PW-D15N   PV-D15N   P	V -D20N												
검출거리 1m 7m 10m 0.1~2m 70mm 300mm 400mm 1~40mm 3~30mm 10~30mm 10~40mm 10~50mm 10~100mm 10~150mm 10	T_DOOD												
	V -D20F												
T 조 기 후 해 OC 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이	~200mm												
표준검출체 Ø6 mm Ø20 mm 백색무광택지 200×200 mm 백색무광택지 100×100 mm 백색무광택지 50×50 mm 백색무광택지 100×100 mm													
정 격 전 압 +12 ~ +24 V DC ±10 % (Ripple ±10 % 이하)													
후 당 부 23m A이하 20m A이하 23 m A이하 30 m A이하 30 m A이하 30 m A이하 30 m A이하	30 mA 이하												
전류 수광부 20mA이하 20mA이어 2													
NPN 오픈콜렉터 출력 /PNP오픈콜렉터 출력, 부하전압 : Max. 30 V DC, 저항부하 : 100mA 이하, 유도 부하 : 50 mA 이하, 잔류전압 : 1 V 이하													
PN오픈콜렉터출력, 부하천압 : Max. 30 V DC, 저항부하 : 50 mA 이하, 잔류전압 : 1 V 이하													
입광(LON)/차광 (DON) 전환스위치로 선택, 볼륨 내장													
Max. 0.7 ms													
동작거리의 20 %이내 동작거리의 10 %이내													
적외발광다이오드 적색발광다이오드 적외발광다이오드 <sub>발광다이오드</sub> 적외발광다이오드 적외발광다이오드 적외발광다이오드													
제어출력 표시등 : 적색 LED, 안정출력 표시등 : 녹색 LED (단, 투과형의 발광부 적색 LED는 전원 표시등임 – PW series는 제외)													
태양광 : 50001x 이하													
사용주위 <b>2도</b> 동작시: -25 ~ +55 ℃, 보존시: -25 ~+70 ℃ (단, 결빙, 결로하지 않을 것)													
<del>사용주위습도</del> 동작시: 35 ~85 % RH, 보존시: 35 ~85 % RH (단, 결로하지 않을 것)													
<u>보호구조</u> IP 67구조	₽67구조												
내 진 동 10~55 Hz (주기 1분간), 복진폭: 1.5 mm, X·Y·Z 각방향 2시간													
내 전 압 1000 V AC (50 / 60 Hz 1분간)	1000 V AC (50 / 60 Hz 1분간)												
내 충 격 500 m/s² (약 50 G), X·Y·Z 각방향 3회													
코드인출식 NPN 4P(투광 2P) 코드인출식 NPN 4P/PNP 3P, 코드인출식 NPN 4P/PNP 3F													
접속방법 /PNP 3P (투광 2P), Ø3 mm, 길이 2 m	·												
Ø3 mm, Zol 2m													
재 질 CASE: PC, Lens Cover: PC													
발·수광부: 각각약 50 g       항 50 g (포장 BOX 문제 제외)       약 50 g (포장 BOX 문제 제외)													
량       약50 g (포장BOX 무게제외)       약80 g (포장BOX 무게제외)													

형사비사형 형사비사형






# 출력회로

#### ■ NPN type의 출력회로


#### ■ PNP tvoe의 출력회로



※투과형의 발광부에는 전원입력만 있습니다. (단,PW series는 측거형만 있음)


## 안정출력에 대하여 -

설정후의 환경변화나 동작 중의 레벨다운 및 동작의 초기 체크로서 사용가능하다. 동작 레벨을 넘어 120% (안전입광영역)에 도달하지 않는 경우, 제어출력이 OFF로 판정해서 출력한다. (단 PNP 출력타입에는 안정출력이 없습니다.)




#### 표시등에 대하여

- 1. 동작표시등 (적색LED), 안정표시등(녹색LED)은 레벨을 표시하고 있습니다.
- 2. 광축조정이나 감도조정 완료후에 검출물체에 따른 입/차광을 반복해서, 안정입/차광 의 영역에 있는지를 확인하여 주십시오.
- 안정영역으로 설정하면 설정후의 환경변화나 기타 이상에 대해서, 보다신뢰성이 높아집니다.




SELECT SW를 LON으로 사용하는 경우는 입광시에 적색 LED가 점등한다. D.ON으로 사용하는 경우는 차광시에 적색 LED가 소등한다.



### 감도조정방법

(입광 동작시-배경에 반사형이 있는 경우의 조정)

- 1. 검출물체를 소정의 위치에 배치한뒤, 감도조정용 볼륨을 서서히 높여가며 동작표시 등이 점등하는 위치를 ③점으로 한다.
- 2. 검출물체가 없는 상태로 감도조정용 볼륨을 최대에서 서서히 낮추어 동작표시등이 소등하는 위치를 ⑥점으로 한다. (최대감도로 해도 동작표시등이 점등하지 않는 경우는, 최대지점(MAX)이 ⑥점이된다.)
- 3. ③점과 ⑤점의 중간에 볼륨을 설정하면 조정 완료된다.




## 검출 방향에 대하여(측거식의 경우)

2분할 포토 다이오드에는 방향성이 있기 때문에 검출물체를 검출할 수 없는 방향이 있으니 주의하여 주십시오.


사용해서는 안되는 방향

: 검출거리 조정용볼륨으로 설정된 검출거리 이내로는 상면의 상하방 향으로도 사용 가능합니다.




# 배경물체에 관하여 (측거식의 경우)

- 광택이 있는 물체나 경면체등이 있는 경우에는 배경물체의 각도에 의하여 오동작을 할수 있으므로 센서를 기울여서 설치하여 주십시오.
- 2. 광택물체(윤기가 있는 표면)를 검출할 경우에는 센서를  $5 \sim 10^\circ$  기울여서 설치하십시오. (그림1)
- 3. 센서의 아랫면에 경면체가 있는 경우, 동작이 불안정해지는 경우가 있으므로 센서를 기 울이던가 아랫면과의 영향을 받지 않는 한도내에서 거리를 두어 설치하십시오. (그림 2)
- 4. 센서의 색, 재질이 극단적으로 변화하는 경우나, 검출면과 검출물체표면과는 반드시 평행이 되도록 설치하여 사용하십시오. (그림3)








#### 검출거리 비교 (확산반사형의 경우 대표 예)

#### ■ 적색 LED type (R40RN)



### ■ 적외 LED type (R30N)

